Completed since last meeting:

Church:

Rear speakers repositioned into nave Access panel fitted to pipe vent in ceiling of RH aisle Pattress fitted around heating pipes close to SW porch doors Wood infestation surveyed External flashing supplemented in SW corner of flat roof Gutter joints sealed Two down-pipes renewed Vestry gate post repaired

Hall:

Disabled toilet tender documents sent out Storm damaged ridge tile replaced Order placed for eastern roof verge repair work Play area fence repaired locally

No 44:

Sundry roof repairs completed New gutter & down-pipe fitted to front porch

No 42:

Various minor roof repairs completed Bath sealant repaired

Planned for next period:

Church:

Treat choir loft, organ structure, electrical cupboard and RH aisle ceiling space for woodworm Investigate high-level ceiling space above organ for woodworm and treat as necessary Obtain prices for repairs to deteriorated external asbestos pipe cladding

Hall:

Obtain quotations for disabled toilet works Complete disabled ramp design and submit for planning permission

No 44:

Nothing planned

No 42:

Annual boiler service and gas safety inspection planned

Generally:

Continue grounds maintenance